



Shaping the Future

November 5, 2014

Mr. Mike Sanders  
State of Connecticut  
Department of Administrative Services  
Division of Construction Services  
165 Capitol Avenue, Room 460  
Hartford, CT 06106

Cardno ATC  
290 Roberts Street  
Suite 301  
East Hartford, CT 06108

Phone +1 860 282 9924  
Fax +1 860 282 9826  
[www.cardno.com](http://www.cardno.com)

[www.cardnoatc.com](http://www.cardnoatc.com)

Re: Asbestos Inspection  
Superintendent Residence  
Seaside Regional Center  
Waterford, Connecticut  
Project MH-14-22  
Building 64656  
Cardno ATC Project 61.22573.0020 Task 20070

Dear Mr. Sanders:

Please find enclosed the Asbestos Inspection Report for the Duplex Residence at Seaside Regional Center located in Waterford, Connecticut.

Should you have any questions concerning this report, do not hesitate to contact me at 860 282-9924 ext. 1123.

Sincerely,

**Cardno ATC**


  
Edward P. Fennell Jr., P.E.  
Division Manager  
for Cardno ATC  
Direct Line +1 860 282 9924 x1123  
Email: [edward.fennell@cardno.com](mailto:edward.fennell@cardno.com)

Encl:

SABdgSci\Clients\CTDPW\61.22573.0020.oncall.services2014\Task20070SeasideSuperintendentResidence\Documents\110514LOT AIR Seaside Superintendent Residence.docx

# **ASBESTOS INSPECTION REPORT**

**SUPERINTENDENT RESIDENCE  
SEASIDE REGIONAL CENTER  
WATERFORD, CONNECTICUT  
BUILDING 64656  
PROJECT MH-14-22**



**STATE OF CONNECTICUT  
DEPARTMENT OF ADMINISTRATIVE SERVICES  
DIVISION OF CONSTRUCTION SERVICES**

**Prepared by:**

**CARDNO ATC  
290 ROBERTS STREET - SUITE 301  
EAST HARTFORD, CT 06108**

**CARDNO ATC PROJECT 61.22573.0020 TASK 20070**

**NOVEMBER 5, 2014**

## **Table of Contents**

---

### **SECTION**

- 1.0 INTRODUCTION**
- 2.0 ASBESTOS-CONTAINING MATERIALS SURVEY**
- 3.0 ASBESTOS-CONTAINING MATERIALS**
- 4.0 DISCUSSION AND RECOMMENDATIONS**
- 5.0 LIMITATIONS**
- 6.0 BULK SAMPLE SUMMARY OF SUSPECT MATERIALS**
- 7.0 BULK SAMPLE RESULTS/CHAIN-OF-CUSTODY FORMS**

**APPENDIX A                  LICENSE AND CERTIFICATION**

**APPENDIX B                  DRAWINGS**

## **1.0 INTRODUCTION**

Cardno ATC (ATC) of East Hartford, Connecticut was retained by the State of Connecticut, Department of Administrative Services, Division of Construction Services (CTDCS) to conduct a limited inspection to identify asbestos-containing materials (ACM) at the Superintendent Residence, Seaside Regional Center, Waterford, Connecticut. The purpose of the investigation was to test suspect materials prior to renovation activities.

The inspection was conducted by Mr. Stanley Szelag and Mr. Willie L Thompson III on October 7-8 2014. Mr. Szelag and Mr. Thompson are State of Connecticut Department of Public Health (CTDPH) licensed asbestos inspectors (CTDPH license numbers 000493 and 00673, respectively). The survey was performed as a walk-through visual inspection, combined with the collection and analysis of bulk samples.

## **2.0 ASBESTOS-CONTAINING MATERIALS SURVEY**

Materials which were considered suspect ACM included: plaster skim and base coats, floor tile and associated mastic, cove base and associated adhesive, pipe insulation, thermal system insulation, gypsum board, joint compound, ceramic floor and wall tile grout and setting compound, window and door caulking, glazing, sink undercoats, roofing materials and miscellaneous caulking and adhesives.

### **2.1 ASBESTOS BULK SAMPLE COLLECTION/ANALYSIS PROCEDURE**

Building materials considered suspect ACM were inspected and assessed using the methods presented in the United States Environmental Protection Agency AHERA regulations (40 CFR Part 763) and NESHAP regulations (40 CFR Part 61).

ATC collected bulk samples of building materials utilizing a sampling strategy that correlated with 40 CFR 763.86 as follows:

- (a) *Surfacing materials.* An accredited inspector shall collect, in a statistically random manner that is representative of the homogeneous area, bulk samples from each homogeneous area of friable surfacing material that is not assumed to be ACM, and shall collect the samples as follows:
  - (1) At least three bulk samples shall be collected from each homogeneous area that is 1,000 ft<sup>2</sup> or less, except as provided in 40 CFR Part 763.87(c)(2).
  - (2) At least five bulk samples shall be collected from each homogeneous area that is greater than 1,000 ft<sup>2</sup> but less than or equal to 5,000 ft<sup>2</sup>, except as provided in 40 CFR Part 763.87(c)(2).
  - (3) At least seven bulk samples shall be collected from each homogeneous area that is greater than 5,000 ft<sup>2</sup>, except as provided in 40 CFR Part 763.87(c)(2).

- (b) *Thermal system insulation.*
- (1) Except as provided in paragraphs (b)(2) through (4) of this section and 40 CFR Part 763.87(c), an accredited inspector shall collect, in a randomly distributed manner, at least three bulk samples from each homogeneous area of thermal system insulation that is not assumed to be ACM.
  - (2) Collect at least one bulk sample from each homogeneous area of patched thermal system insulation that is not assumed to be ACM if the patched section is less than 6 linear or square feet.
  - (3) In a manner sufficient to determine whether the material is ACM or not ACM, collect bulk samples from each insulated mechanical system that is not assumed to be ACM where cement or plaster is used on fittings such as tees, elbows, or valves, except as provided under 40 CFR Part 763.87(c)(2).
  - (4) Bulk samples are not required to be collected from any homogeneous area where the accredited inspector has determined that the thermal system insulation is fiberglass, foam glass, rubber, or other non-ACM.
- (c) *Miscellaneous materials.* In a manner sufficient to determine whether material is ACM or not ACM, an accredited inspector shall collect bulk samples from each homogeneous area of friable or non-friable miscellaneous material that is not assumed to be ACM.

The bulk samples collected during the survey were analyzed by EMSL Analytical, Inc. (NVLAP Lab Code 101048-9) located in New York, New York. The bulk samples were analyzed by Polarized Light Microscopy (PLM) with dispersion staining via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s). Utilizing PLM, the microscopist is able to identify and distinguish between asbestos group minerals and other fibrous materials such as cellulose, mineral wool, fiberglass, or synthetic fibers. The quantities of each of these substances is estimated based on the procedures defined in the above-cited reference and are reported as a percentage.

The EPA recognizes the following as asbestos: Chrysotile, Crocidolite, Amosite, Tremolite, Actinolite, and Anthophyllite. To be classified as ACM, the material must be determined to contain greater than one percent (1%) asbestos. In order to consider a material to be non-ACM, all samples of a homogeneous type of material that are collected must be analyzed and all results must indicate the material to contain less than 1% asbestos by weight.

### **3.0 ASBESTOS-CONTAINING MATERIALS**

The results of PLM laboratory analysis indicated that the following materials are asbestos-containing material (ACM). ACM are those materials that contain greater than 1% asbestos, and are as follows:

- Air Cell Pipe Insulation
- Red/Blue Flooring and Associated Adhesive
- 9"x9" Gray Floor Tile
- 2'x4' Ceiling Tile (Small Hole Pattern)
- Air Cell Pipe Insulation
- Muddled Pipe Fitting Insulation
- Breeching Insulation
- Black Sink Undercoating

- Exterior Door Frame Caulk
- Exterior Window Caulking(wood window systems)
- Exterior Window Caulking
- Caulking at Gutters (Above Garage/Family Room)

The remaining materials which were sampled and tested were found to contain no detectable amounts of asbestos. Specifically, the following materials were determined to be non-ACM:

- Plaster Wall - Skim Coat
- Plaster Wall - Base Coat
- Plaster Ceiling - Skim Coat
- Plaster Ceiling - Base Coat
- Plaster Ceiling Base Coat #2
- One Coat Plaster
- Gypsum Board
- Joint Compound
- Tan Sheet Flooring and Associated Adhesive
- Ceramic Floor Tile Setting Compound and Grout(Gray)
- Ceramic Wall Tile Setting Compound and Grout (Gray/White)
- Ceramic Wall Tile Setting Compound and Grout (/Gray/White)
- 4" Brown Cove Base and Associated Adhesive
- 2'x4' Ceiling Tile Streaked
- Peg Board Glue Daub (Brown)
- Flue Cement
- Tar Paper under Slate Roof
- Metal Window Glazing
- Exterior Wood Window Glazing
- Wool-like Insulation
- Black Wire Insulation
- White Wire Insulation
- Foundation Damp Proof Tar
- Reflective Paper Insulation on Exterior Lighting

Refer to Section 6.0, Bulk Sample Summary of Suspect Materials, for all suspect materials that were identified and sampled.

#### **4.0 DISCUSSION AND RECOMMENDATIONS**

EPA regulations require the removal of Regulated Asbestos-Containing Materials (RACM) prior to renovation or demolition activities. RACM is defined as (a) Friable ACM, (b) Category I non-friable ACM that has become friable, (c) Category I non-friable ACM that will be or has been subjected to sanding, grinding, cutting, or abrading, or (d) Category II non-friable ACM that has a high probability of becoming or has become crumbled, pulverized, or reduced to powder by the forces expected to act on the material in the course of demolition or renovation activities. The CTDPH defines "asbestos abatement" as removal, encapsulation, enclosure, renovation, repair, demolition, or other disturbance of ACM but does not include activities which are related to (A) the removal or repair of asbestos cement pipe and are performed by employees of a water company as defined in section 25-32a, or (B) the removal of non-

friable ACM found exterior to a building or structure other than material defined as RACM in 40 CFR 61, the National Emission Standards for Hazardous Air Pollutants (NESHAP). Based upon these definitions, ACM identified in the building requires removal prior to renovation, demolition, or disturbance. The State of Connecticut, Department of Energy and Environmental Protection (CTDEEP) regulations require the proper disposal of all ACM, regardless of categorization.

## **5.0 LIMITATIONS**

As with all such assessments, the results of the sampling represent conditions found on the date of the survey and may not represent conditions found at other times. Additionally, this assessment was limited with respect to the specific parameters indicated above and should not be construed to be a comprehensive evaluation or a definitive representation of conditions within the facility. The information presented in this report is intended to be used as a guide to evaluate the need for further investigation or the need for modifications to the processes or procedures surveyed.

## **6.0 BULK SAMPLE SUMMARY OF SUSPECT MATERIALS**

**TABLE 6-1**  
**BULK SAMPLE SUMMARY OF SUSPECT MATERIALS**  
**SEASIDE REGIONAL CENTER**  
**SUPERINTENDENT RESIDENCE**

<b>Sample Number</b>	<b>Sample Location</b>	<b>Material</b>	<b>% Asbestos</b>	<b>Asbestos Type</b>
<b>100814-SH-1A</b>	<b>1st Floor Family Room</b>	<b>Red/Blue Floor Covering</b>	<b>5</b>	<b>Chrysotile</b>
<b>100814-SH-1B</b>	<b>1st Floor Family Room</b>	<b>Red/Blue Floor Covering</b>	<b>3</b>	<b>Chrysotile</b>
<b>100814-SH-2A</b>	<b>1st Floor Family Room</b>	<b>Black Mastic For Red/Blue Floor Covering</b>	<b>8</b>	<b>Chrysotile</b>
<b>100814-SH-2B</b>	<b>1st Floor Family Room</b>	<b>Black Mastic For Red/Blue Floor Covering</b>	<b>5</b>	<b>Chrysotile</b>
100814-SH-3A	Kitchen	Tan Sheet Flooring	ND	
100814-SH-3B	Kitchen	Tan Sheet Flooring	ND	
100814-SH-4A	Kitchen	Tan Flooring Adhesive	ND	
100814-SH-4B	Kitchen	Tan Flooring Adhesive	ND	
<b>100814-SH-5A</b>	<b>Kitchen</b>	<b>Black Sink Undercoat</b>	<b>10</b>	<b>Chrysotile</b>
<b>100814-SH-5B</b>	<b>Kitchen</b>	<b>Black Sink Undercoat</b>	<b>8</b>	<b>Chrysotile</b>
100814-SH-6A	Main Entrance	1 - Coat Wall Plaster	ND	
100814-SH-6B	Living Room	1 - Coat Wall Plaster	ND	
100814-SH-6C	Stair Well	1 - Coat Wall Plaster	ND	
100814-SH-6D	1st Floor Jon Room	1 - Coat Wall Plaster	ND	
100814-SH-6E	2nd Floor Hallway	1 - Coat Wall Plaster	ND	
100814-SH-7A	M. Entrance	1 - Coat Ceiling Plaster	ND	
100814-SH-7B	1st Floor Hall	1 - Coat Ceiling Plaster	ND	
100814-SH-7C	Sun Room	1- Coat Ceiling Plaster	ND	
100814-SH-7D	1st Floor Side Room	1 - Coat Ceiling Plaster	ND	
100814-SH-7E	2nd Floor Bed Room- 2	1 - Coat Ceiling Plaster	ND	

**TABLE 6-1**  
**BULK SAMPLE SUMMARY OF SUSPECT MATERIALS**  
**SEASIDE REGIONAL CENTER**  
**SUPERINTENDENT RESIDENCE**

<b>Sample Number</b>	<b>Sample Location</b>	<b>Material</b>	<b>% Asbestos</b>	<b>Asbestos Type</b>
100814-SH-8A	Kitchen	Wall Plaster - Scratch Coat	ND	
100814-SH-8B	Side Room	Wall Plaster - Scratch Coat	ND	
100814-SH-8C	2nd Floor East Entrance	Wall Plaster - Scratch Coat	ND	
100814-SH-8D	2nd Floor Main Bed Room	Wall Plaster - Scratch Coat	ND	
100814-SH-8E	2nd Floor Bed Room 1	Wall Plaster - Scratch Coat	ND	
100814-SH-9A	Kitchen	Wall Plaster - Skim Coat	ND	
100814-SH-9B	1st Floor Side Room	Wall Plaster - Skim Coat	ND	
100814-SH-9C	2nd Floor East Entry	Wall Plaster - Skim Coat	ND	
100814-SH-9D	2nd Floor M. Bed Room	Wall Plaster - Skim Coat	ND	
100814-SH-9E	2nd Floor Bed Room 1	Wall Plaster - Skim Coat	ND	
100814-SH-10A	Living Room # 2	Ceiling Plaster - Scratch Coat - 2	ND	
100814-SH-10B	Living Room # 2	Ceiling Plaster - Scratch Coat - 2	ND	
100814-SH-10C	Kitchen	Ceiling Plaster - Scratch Coat - 2	ND	
100814-SH-10D	Dining Room # 2	Ceiling Plaster - Scratch Coat - 2	ND	
100814-SH-10E	2nd Fl Bed Room- 1	Ceiling Plaster - Scratch Coat - 2	ND	
100814-SH-11A	Living Room # 2	Ceiling Plaster - Skim Coat	ND	
100814-SH-11B	Living Room # 2	Ceiling Plaster - Skim Coat	ND	
100814-SH-11C	Kitchen	Ceiling Plaster - Skim Coat	ND	
100814-SH-11D	Dining Room # 2	Ceiling Plaster - Skim Coat	ND	
100814-SH-11E	2nd Floor Bed Room - 1	Ceiling Plaster - Skim Coat	ND	

**TABLE 6-1**  
**BULK SAMPLE SUMMARY OF SUSPECT MATERIALS**  
**SEASIDE REGIONAL CENTER**  
**SUPERINTENDENT RESIDENCE**

<b>Sample Number</b>	<b>Sample Location</b>	<b>Material</b>	<b>% Asbestos</b>	<b>Asbestos Type</b>
100814-SH-12A	2nd Floor South West Room	Ceiling Plaster - Scratch Coat	ND	
100814-SH-12B	Master Bed Room	Ceiling Plaster - Scratch Coat	ND	
100814-SH-12C	Rear Bed Room	Ceiling Plaster - Scratch Coat	ND	
100814-SH-13A	2nd Floor Sun Room	Ceiling Plaster - Scratch Coat	ND	
100814-SH-13B	2nd Floor Mid Room	Ceiling Plaster - Scratch Coat	ND	
100814-SH-13C	2nd Floor Rear Bath	Ceiling Plaster - Scratch Coat	ND	
100814-SH-14A	1st Floor Bath	Ceramic Floor Tile Setting Compound	ND	
100814-SH-14B	1st Floor Bath	Ceramic Floor Tile Setting Compound	ND	
100814-SH-15A	1st Floor Bath	Ceramic Floor Tile Grout	ND	
100814-SH-15B	1st Floor Bath	Ceramic Floor Tile Grout	ND	
100814-SH-16A	2nd Floor Master Bath	Ceramic Floor Tile Setting Compound	ND	
100814-SH-16B	2nd Floor Master Bath	Ceramic Floor Tile Setting Compound	ND	
100814-SH-17A	2nd Floor Master Bath	Ceramic Floor Tile Grout	ND	
100814-SH-17B	2nd Floor Master Bath	Ceramic Floor Tile Grout	ND	
100814-SH-18A	2nd Floor Master Bath	Ceramic Wall Tile Setting Compound	ND	
100814-SH-18B	2nd Floor Master Bath	Ceramic Wall Tile Setting Compound	ND	
100814-SH-18C	Bath # 2	Ceramic Wall Tile Setting Compound	ND	
100814-SH-19A	2nd Floor Master Bath	Ceramic Wall Tile Grout	ND	
100814-SH-19B	2nd Floor Master Bath	Ceramic Wall Tile Grout	ND	
100814-SH-19C	Bath # 2	Ceramic Wall Tile Grout	ND	

**TABLE 6-1**  
**BULK SAMPLE SUMMARY OF SUSPECT MATERIALS**  
**SEASIDE REGIONAL CENTER**  
**SUPERINTENDENT RESIDENCE**

<b>Sample Number</b>	<b>Sample Location</b>	<b>Material</b>	<b>% Asbestos</b>	<b>Asbestos Type</b>
100814-SH-20A	2nd Floor Bath 2	Ceramic Floor Tile Setting Compound	ND	
100814-SH-20B	2nd Floor Bath 3	Ceramic Floor Tile Setting Compound	ND	
100814-SH-21A	2nd Floor Bath 2	Ceramic Floor Tile Grout	ND	
100814-SH-21B	2nd Floor Bath 3	Ceramic Floor Tile Grout	ND	
100814-SH-22A	Kitchen	4" Brown Cove Base	ND	
100814-SH-22B	Kitchen	4" Brown Cove Base	ND	
100814-SH-23A	Kitchen	4" Brown Cove Base Adhesive	ND	
100814-SH-23B	Kitchen	4" Brown Cove Base Adhesive	ND	
100814-SH-24A	Basement	Peg Board Glue Daub-Brown	ND	
100814-SH-24B	Basement	Peg Board Glue Daub-Brown	ND	
<b>100814-SH-25A</b>	<b>Basement</b>	<b>9"X9" Gray Floor Tile</b>	<b>5</b>	<b>Chrysotile</b>
<b>100814-SH-25B</b>	<b>Basement</b>	<b>9"X9" Gray Floor Tile</b>	<b>6</b>	<b>Chrysotile</b>
100814-SH-26A	Basement	Black Mastic for 9"X9" Gray Floor Tile	ND	
100814-SH-26B	Basement	Black Mastic for 9"X9" Gray Floor Tile	ND	
100814-SH-27A	Basement Boiler Room	Flue Cement	ND	
100814-SH-27B	Basement Boiler Room	Flue Cement	ND	
100814-SH-28A	Basement	2'X4' Ceiling Tile Streaked	ND	
100814-SH-28B	Basement	2'X4' Ceiling Tile Streaked	ND	
<b>100814-SH-29A</b>	<b>Basement</b>	<b>2'X4' Ceiling Tile Small Hole</b>	<b>9</b>	<b>Amosite</b>
<b>100814-SH-29B</b>	<b>Basement</b>	<b>2'X4' Ceiling Tile Small Hole</b>	<b>5</b>	<b>Amosite</b>

**TABLE 6-1**  
**BULK SAMPLE SUMMARY OF SUSPECT MATERIALS**  
**SEASIDE REGIONAL CENTER**  
**SUPERINTENDENT RESIDENCE**

Sample Number	Sample Location	Material	% Asbestos	Asbestos Type
100814-SH-30A	Family Room	Aircell Pipe Insulation	55	Chrysotile
100814-SH-30B	Laundry Room	Aircell Pipe Insulation	25	Chrysotile
100814-SH-30C	Basement	Aircell Pipe Insulation	40	Chrysotile
100814-SH-31A	Laundry Room	Muddled Pipe Fitting Insulation	35	Chrysotile
100814-SH-31B	Basement	Muddled Pipe Fitting Insulation	3 50	Chrysotile Amosite
100814-SH-31C	Basement	Muddled Pipe Fitting Insulation	5 35	Chrysotile Amosite
100814-SH-32A	Basement Boiler Room	Breeching Insulation	30	Chrysotile
100814-SH-32B	Basement Boiler Room	Breeching Insulation	35	Chrysotile
100814-SH-32C	Basement Boiler Room	Breeching Insulation	45	Chrysotile
100814-SH-33A	Exterior Roof	Tar Paper Under Slate Roof	ND	
100814-SH-33B	Exterior Roof	Tar Paper Under Slate Roof	ND	
100814-SH-34A	Kitchen-Exterior	Metal Window Glazing	ND	
100814-SH-34B	Kitchen-Exterior	Metal Window Glazing	ND	
100814-SH-35A	Living Room	Exterior Wood Window Glazing	ND	
100814-SH-35B	East Entrance	Exterior Wood Window Glazing	ND	
100814-SH-36A	Exterior	Storm Window Caulk	5	Chrysotile
100814-SH-36B	Exterior	Storm Window Caulk	4	Chrysotile
100814-SH-37A	Dining Room	Exterior Wood Window Caulk	10	Chrysotile
100814-SH-37B	Living Room	Exterior Wood Window Caulk	6	Chrysotile
100814-SH-38A	Entrance Door	Door Frame Caulk	6	Chrysotile

**TABLE 6-1**  
**BULK SAMPLE SUMMARY OF SUSPECT MATERIALS**  
**SEASIDE REGIONAL CENTER**  
**SUPERINTENDENT RESIDENCE**

<b>Sample Number</b>	<b>Sample Location</b>	<b>Material</b>	<b>% Asbestos</b>	<b>Asbestos Type</b>
<b>100814-SH-38B</b>	<b>Entrance Door</b>	<b>Door Frame Caulk</b>	<b>4</b>	<b>Chrysotile</b>
100814-SH-39A	Attic	Wool Like Insulation	ND	
100814-SH-39B	Attic	Wool Like Insulation	ND	
100814-SH-40A	House Interior	House Wire Insulation Black	ND	
100814-SH-40B	House Interior	House Wire Insulation Black	ND	
100814-SH-41A	House Interior	House Wire Insulation White	ND	
100814-SH-41B	House Interior	House Wire Insulation White	ND	
100814-SH-42A	Foundation	Damp Proof Tar	ND	
100814-SH-42B	Foundation	Damp Proof Tar	ND	
<b>100814-SH-43A</b>	<b>Exterior Gutters</b>	<b>Caulking on Gutters</b>	<b>5</b>	<b>Chrysotile</b>
<b>100814-SH-43B</b>	<b>Exterior Gutters</b>	<b>Caulking on Gutters</b>	<b>4</b>	<b>Chrysotile</b>
100814-SH-44A	Building Exterior	Reflective Paper Insulation	ND	
100814-SH-44B	Building Exterior	Reflective Paper Insulation	ND	

ND = None Detected

## **7.0 BULK SAMPLE RESULTS/CHAIN-OF-CUSTODY FORMS**



# EMSL Analytical, Inc.

307 West 38th Street New York, NY 10018  
 Phone/Fax: (212) 290-0051 / (212) 290-0058  
<http://www.EMSL.com> / manhattanlab@emsl.com

EMSL Order ID:	031440897
Customer ID:	ATCE54
Customer PO:	14-061-0001A
Project ID:	

**Attn:** Ed Fennell  
 Cardno ATC  
 290 Roberts Street  
 Suite 301  
 East Hartford, CT 06108

**Phone:** (860) 282-9924  
**Fax:** (860) 282-9826  
**Collected:** 10/ 8/2014  
**Received:** 10/23/2014  
**Analyzed:** 10/24/2014

**Proj:** 61.225T3.0020T20070/ CT DCS/ SUPERINTENDENT HOUSE/ SEASIDE HOSP COMPLEX/ 36 SHORE RD  
 WATER FORT CT

## Summary Test Report for Asbestos Analysis in Accordance with N.J.A.C. 8:60 and 12:120 via EPA 600/R-93/116

**Client Sample ID:** 100814-SH-1A

**Lab Sample ID:** 031440897-0001

**Sample Description:** 1ST FL FAMILY RM/RED/ BLUE FLR COVERING

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	10/23/2014	Gray	0%	95%	5% Chrysotile	

**Client Sample ID:** 100814-SH-1B

**Lab Sample ID:** 031440897-0002

**Sample Description:** 1ST FL FAMILY RM/RED/ BLUE FLR COVERING

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	10/24/2014	Brown/Black	0%	97%	3% Chrysotile	

**Client Sample ID:** 100814-SH-2A

**Lab Sample ID:** 031440897-0003

**Sample Description:** 1ST FL FAMILY RM/RED/ BLUE FLR COVERING

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	10/23/2014	Black	0%	92%	8% Chrysotile	

**Client Sample ID:** 100814-SH-2B

**Lab Sample ID:** 031440897-0004

**Sample Description:** 1ST FL FAMILY RM/MASTIC- BLK

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	10/24/2014	Black	0%	95%	5% Chrysotile	

**Client Sample ID:** 100814-SH-3A

**Lab Sample ID:** 031440897-0005

**Sample Description:** KITCHEN/TAN SHEET FLOORING

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	10/23/2014	Gray	7%	93%	None Detected	

**Client Sample ID:** 100814-SH-3B

**Lab Sample ID:** 031440897-0006

**Sample Description:** KITCHEN/TAN SHEET FLOORING

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	10/24/2014	Gray	10%	90%	None Detected	

**Client Sample ID:** 100814-SH-4A

**Lab Sample ID:** 031440897-0007

**Sample Description:** KITCHEN/ADHESIVE TAN FLOORING

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	10/23/2014	Black	45%	55%	None Detected	



# EMSL Analytical, Inc.

307 West 38th Street New York, NY 10018  
 Phone/Fax: (212) 290-0051 / (212) 290-0058  
<http://www.EMSL.com> / manhattanlab@emsl.com

EMSL Order ID:	031440897
Customer ID:	ATCE54
Customer PO:	14-061-0001A
Project ID:	

## Summary Test Report for Asbestos Analysis in Accordance with N.J.A.C. 8:60 and 12:120 via EPA 600/R-93/116

<b>Client Sample ID:</b>	100814-SH-4B	<b>Lab Sample ID:</b>	031440897-0008												
<b>Sample Description:</b> KITCHEN/ADHESIVE TAN FLOORING															
<table> <thead> <tr> <th>TEST</th><th>Analyzed Date</th><th>Color</th><th>Non-Asbestos Fibrous Non-Fibrous</th><th>Asbestos</th><th>Comment</th></tr> </thead> <tbody> <tr> <td>PLM</td><td>10/24/2014</td><td>Gray/Black</td><td>35% 65%</td><td>None Detected</td><td></td></tr> </tbody> </table>				TEST	Analyzed Date	Color	Non-Asbestos Fibrous Non-Fibrous	Asbestos	Comment	PLM	10/24/2014	Gray/Black	35% 65%	None Detected	
TEST	Analyzed Date	Color	Non-Asbestos Fibrous Non-Fibrous	Asbestos	Comment										
PLM	10/24/2014	Gray/Black	35% 65%	None Detected											
<b>Client Sample ID:</b>	100814-SH-5A	<b>Lab Sample ID:</b>	031440897-0009												
<b>Sample Description:</b> KITCHEN/BLACK SINK UNDERCOAT															
<table> <thead> <tr> <th>TEST</th><th>Analyzed Date</th><th>Color</th><th>Non-Asbestos Fibrous Non-Fibrous</th><th>Asbestos</th><th>Comment</th></tr> </thead> <tbody> <tr> <td>PLM</td><td>10/23/2014</td><td>Black</td><td>0% 90%</td><td>10% Chrysotile</td><td></td></tr> </tbody> </table>				TEST	Analyzed Date	Color	Non-Asbestos Fibrous Non-Fibrous	Asbestos	Comment	PLM	10/23/2014	Black	0% 90%	10% Chrysotile	
TEST	Analyzed Date	Color	Non-Asbestos Fibrous Non-Fibrous	Asbestos	Comment										
PLM	10/23/2014	Black	0% 90%	10% Chrysotile											
<b>Client Sample ID:</b>	100814-SH-5B	<b>Lab Sample ID:</b>	031440897-0010												
<b>Sample Description:</b> KITCHEN/BLACK SINK UNDERCOAT															
<table> <thead> <tr> <th>TEST</th><th>Analyzed Date</th><th>Color</th><th>Non-Asbestos Fibrous Non-Fibrous</th><th>Asbestos</th><th>Comment</th></tr> </thead> <tbody> <tr> <td>PLM</td><td>10/24/2014</td><td>Black</td><td>0% 92%</td><td>8% Chrysotile</td><td></td></tr> </tbody> </table>				TEST	Analyzed Date	Color	Non-Asbestos Fibrous Non-Fibrous	Asbestos	Comment	PLM	10/24/2014	Black	0% 92%	8% Chrysotile	
TEST	Analyzed Date	Color	Non-Asbestos Fibrous Non-Fibrous	Asbestos	Comment										
PLM	10/24/2014	Black	0% 92%	8% Chrysotile											
<b>Client Sample ID:</b>	100814-SH-6A	<b>Lab Sample ID:</b>	031440897-0011												
<b>Sample Description:</b> M. ENTRANCE/1- COAT WALL PLASTER															
<table> <thead> <tr> <th>TEST</th><th>Analyzed Date</th><th>Color</th><th>Non-Asbestos Fibrous Non-Fibrous</th><th>Asbestos</th><th>Comment</th></tr> </thead> <tbody> <tr> <td>PLM</td><td>10/23/2014</td><td>Tan</td><td>0% 100%</td><td>None Detected</td><td></td></tr> </tbody> </table>				TEST	Analyzed Date	Color	Non-Asbestos Fibrous Non-Fibrous	Asbestos	Comment	PLM	10/23/2014	Tan	0% 100%	None Detected	
TEST	Analyzed Date	Color	Non-Asbestos Fibrous Non-Fibrous	Asbestos	Comment										
PLM	10/23/2014	Tan	0% 100%	None Detected											
<b>Client Sample ID:</b>	100814-SH-6B	<b>Lab Sample ID:</b>	031440897-0012												
<b>Sample Description:</b> LIVING RM/1- COAT WALL PLASTER															
<table> <thead> <tr> <th>TEST</th><th>Analyzed Date</th><th>Color</th><th>Non-Asbestos Fibrous Non-Fibrous</th><th>Asbestos</th><th>Comment</th></tr> </thead> <tbody> <tr> <td>PLM</td><td>10/23/2014</td><td>Tan</td><td>0% 100%</td><td>None Detected</td><td></td></tr> </tbody> </table>				TEST	Analyzed Date	Color	Non-Asbestos Fibrous Non-Fibrous	Asbestos	Comment	PLM	10/23/2014	Tan	0% 100%	None Detected	
TEST	Analyzed Date	Color	Non-Asbestos Fibrous Non-Fibrous	Asbestos	Comment										
PLM	10/23/2014	Tan	0% 100%	None Detected											
<b>Client Sample ID:</b>	100814-SH-6C	<b>Lab Sample ID:</b>	031440897-0013												
<b>Sample Description:</b> STAIR WELL/1- COAT WALL PLASTER															
<table> <thead> <tr> <th>TEST</th><th>Analyzed Date</th><th>Color</th><th>Non-Asbestos Fibrous Non-Fibrous</th><th>Asbestos</th><th>Comment</th></tr> </thead> <tbody> <tr> <td>PLM</td><td>10/23/2014</td><td>Gray</td><td>2% 98%</td><td>None Detected</td><td></td></tr> </tbody> </table>				TEST	Analyzed Date	Color	Non-Asbestos Fibrous Non-Fibrous	Asbestos	Comment	PLM	10/23/2014	Gray	2% 98%	None Detected	
TEST	Analyzed Date	Color	Non-Asbestos Fibrous Non-Fibrous	Asbestos	Comment										
PLM	10/23/2014	Gray	2% 98%	None Detected											
<b>Client Sample ID:</b>	100814-SH-6D	<b>Lab Sample ID:</b>	031440897-0014												
<b>Sample Description:</b> 1ST FLR JON RM/1- COAT WALL PLASTER															
<table> <thead> <tr> <th>TEST</th><th>Analyzed Date</th><th>Color</th><th>Non-Asbestos Fibrous Non-Fibrous</th><th>Asbestos</th><th>Comment</th></tr> </thead> <tbody> <tr> <td>PLM</td><td>10/23/2014</td><td>Gray</td><td>2% 98%</td><td>None Detected</td><td></td></tr> </tbody> </table>				TEST	Analyzed Date	Color	Non-Asbestos Fibrous Non-Fibrous	Asbestos	Comment	PLM	10/23/2014	Gray	2% 98%	None Detected	
TEST	Analyzed Date	Color	Non-Asbestos Fibrous Non-Fibrous	Asbestos	Comment										
PLM	10/23/2014	Gray	2% 98%	None Detected											
<b>Client Sample ID:</b>	100814-SH-6E	<b>Lab Sample ID:</b>	031440897-0015												
<b>Sample Description:</b> 2ND FLR HALLWAY/1- COAT WALL PLASTER															
<table> <thead> <tr> <th>TEST</th><th>Analyzed Date</th><th>Color</th><th>Non-Asbestos Fibrous Non-Fibrous</th><th>Asbestos</th><th>Comment</th></tr> </thead> <tbody> <tr> <td>PLM</td><td>10/24/2014</td><td>Gray</td><td>0% 100%</td><td>None Detected</td><td></td></tr> </tbody> </table>				TEST	Analyzed Date	Color	Non-Asbestos Fibrous Non-Fibrous	Asbestos	Comment	PLM	10/24/2014	Gray	0% 100%	None Detected	
TEST	Analyzed Date	Color	Non-Asbestos Fibrous Non-Fibrous	Asbestos	Comment										
PLM	10/24/2014	Gray	0% 100%	None Detected											



# EMSL Analytical, Inc.

307 West 38th Street New York, NY 10018  
Phone/Fax: (212) 290-0051 / (212) 290-0058  
<http://www.EMSL.com> / manhattanlab@emsl.com

EMSL Order ID: 031440897  
Customer ID: ATCE54  
Customer PO: 14-061-0001A  
Project ID:

## Summary Test Report for Asbestos Analysis in Accordance with N.J.A.C. 8:60 and 12:120 via EPA 600/R-93/116

<b>Client Sample ID:</b> 100814-SH-7A	<b>Lab Sample ID:</b> 031440897-0016																		
<b>Sample Description:</b> M. ENTRANCE/1- COAT CEILING PLASTER																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	Gray	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-7B	<b>Lab Sample ID:</b> 031440897-0017																		
<b>Sample Description:</b> 1ST FLR HALL/1- COAT CEILING PLASTER																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	Gray	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-7C	<b>Lab Sample ID:</b> 031440897-0018																		
<b>Sample Description:</b> SUN RM/1- COAT CEILING PLASTER																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	Gray	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-7D	<b>Lab Sample ID:</b> 031440897-0019																		
<b>Sample Description:</b> 1ST FLR SIDE RM/1- COAT CEILING PLASTER																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	Gray	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-7E	<b>Lab Sample ID:</b> 031440897-0020																		
<b>Sample Description:</b> 2ND FL AID RM- 2/1- COAT CEILING PLASTER																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/24/2014	Gray	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-8A	<b>Lab Sample ID:</b> 031440897-0021																		
<b>Sample Description:</b> KITCHEN/WALL PLASTER- SCRATCH COAT																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	Gray	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-8B	<b>Lab Sample ID:</b> 031440897-0022																		
<b>Sample Description:</b> SIDE RM/WALL PLASTER- SCRATCH COAT																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	Gray	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-8C	<b>Lab Sample ID:</b> 031440897-0023																		
<b>Sample Description:</b> 2ND FLR E. ENT/WALL PLASTER- SCRATCH COAT																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	Gray	0%	100%	None Detected														



# EMSL Analytical, Inc.

307 West 38th Street New York, NY 10018  
Phone/Fax: (212) 290-0051 / (212) 290-0058  
<http://www.EMSL.com> / manhattanlab@emsl.com

EMSL Order ID: 031440897  
Customer ID: ATCE54  
Customer PO: 14-061-0001A  
Project ID:

## Summary Test Report for Asbestos Analysis in Accordance with N.J.A.C. 8:60 and 12:120 via EPA 600/R-93/116

<b>Client Sample ID:</b> 100814-SH-8D	<b>Lab Sample ID:</b> 031440897-0024																		
<b>Sample Description:</b> 2ND FLR M. BED RM/WALL PLASTER- SCRATCH COAT																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	Gray	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-8E	<b>Lab Sample ID:</b> 031440897-0025																		
<b>Sample Description:</b> 2ND FLR BED RM 1/WALL PLASTER- SCRATCH COAT																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/24/2014	Gray	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-9A	<b>Lab Sample ID:</b> 031440897-0026																		
<b>Sample Description:</b> KITCHEN/WL PLASTER SKIM COAT																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>White</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	White	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	White	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-9B	<b>Lab Sample ID:</b> 031440897-0027																		
<b>Sample Description:</b> 1ST FLR SIDE RM/WL PLASTER SKIM COAT																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>White</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	White	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	White	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-9C	<b>Lab Sample ID:</b> 031440897-0028																		
<b>Sample Description:</b> 2ND FLR E. ENY/WL PLASTER SKIM COAT																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>White</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	White	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	White	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-9D	<b>Lab Sample ID:</b> 031440897-0029																		
<b>Sample Description:</b> 2ND FLR M. BED RM/WL PLASTER SKIM COAT																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>White</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	White	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	White	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-9E	<b>Lab Sample ID:</b> 031440897-0030																		
<b>Sample Description:</b> 2ND FLR BED RM 1/WL PLASTER SKIM COAT																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>White</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	White	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/24/2014	White	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-10A	<b>Lab Sample ID:</b> 031440897-0031																		
<b>Sample Description:</b> LIVING RM # 2/CEILING PLASTER SCRATCH COAT- 2																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	Gray	0%	100%	None Detected														



# EMSL Analytical, Inc.

307 West 38th Street New York, NY 10018  
Phone/Fax: (212) 290-0051 / (212) 290-0058  
<http://www.EMSL.com> / manhattanlab@emsl.com

EMSL Order ID: 031440897  
Customer ID: ATCE54  
Customer PO: 14-061-0001A  
Project ID:

## Summary Test Report for Asbestos Analysis in Accordance with N.J.A.C. 8:60 and 12:120 via EPA 600/R-93/116

<b>Client Sample ID:</b> 100814-SH-10B	<b>Lab Sample ID:</b> 031440897-0032																		
<b>Sample Description:</b> LIV RM # 2/CEILING PLASTER SCRATCH COAT- 2																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	Gray	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-10C	<b>Lab Sample ID:</b> 031440897-0033																		
<b>Sample Description:</b> KITCHEN/CEILING PLASTER SCRATCH COAT- 2																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	Gray	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-10D	<b>Lab Sample ID:</b> 031440897-0034																		
<b>Sample Description:</b> DINING RM # 2/CEILING PLASTER SCRATCH COAT																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	Gray	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-10E	<b>Lab Sample ID:</b> 031440897-0035																		
<b>Sample Description:</b> 2ND FL BED RM- 1/CEILING PLASTER SCRATCH COAT																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/24/2014	Gray	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-11A	<b>Lab Sample ID:</b> 031440897-0036																		
<b>Sample Description:</b> LIVING RM # 2/CEILING PLASTER SKIM COAT																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	Gray	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-11B	<b>Lab Sample ID:</b> 031440897-0037																		
<b>Sample Description:</b> LIVING RM # 2/CEILING PLASTER SKIM COAT																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	Gray	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-11C	<b>Lab Sample ID:</b> 031440897-0038																		
<b>Sample Description:</b> KITCH/CEILING PLASTER SKIM COAT																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>White</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	White	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	White	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-11D	<b>Lab Sample ID:</b> 031440897-0039																		
<b>Sample Description:</b> DINING RM # 2/CEILING PLASTER SKIM COAT																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>White</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	White	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	White	0%	100%	None Detected														



# EMSL Analytical, Inc.

307 West 38th Street New York, NY 10018  
Phone/Fax: (212) 290-0051 / (212) 290-0058  
<http://www.EMSL.com> / manhattanlab@emsl.com

EMSL Order ID: 031440897  
Customer ID: ATCE54  
Customer PO: 14-061-0001A  
Project ID:

## Summary Test Report for Asbestos Analysis in Accordance with N.J.A.C. 8:60 and 12:120 via EPA 600/R-93/116

<b>Client Sample ID:</b> 100814-SH-11E	<b>Lab Sample ID:</b> 031440897-0040																		
<b>Sample Description:</b> 2ND FLR BED RM - 1/CEILING PLASTER SKIM COAT																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>White</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	White	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/24/2014	White	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-12A	<b>Lab Sample ID:</b> 031440897-0041																		
<b>Sample Description:</b> 2ND FLR SW RM/CEILING PLASTER SCRATCH COAT																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	Gray	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-12B	<b>Lab Sample ID:</b> 031440897-0042																		
<b>Sample Description:</b> MID BED RM/CEILING PLASTER SCRATCH COAT																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	Gray	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-12C	<b>Lab Sample ID:</b> 031440897-0043																		
<b>Sample Description:</b> REAR BED RM/CEILING PLASTER SCRATCH COAT																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/24/2014	Gray	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-13A	<b>Lab Sample ID:</b> 031440897-0044																		
<b>Sample Description:</b> 2ND FLR SUN RM/CEILING PLASTER SCRATCH COAT																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>White</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	White	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	White	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-13B	<b>Lab Sample ID:</b> 031440897-0045																		
<b>Sample Description:</b> 2ND FLR MID RM/CEILING PLASTER SCRATCH COAT																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>White</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	White	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	White	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-13C	<b>Lab Sample ID:</b> 031440897-0046																		
<b>Sample Description:</b> 2ND FLR REAR BATH/CEILING PLASTER SCRATCH COAT																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>White</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	White	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	White	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-14A	<b>Lab Sample ID:</b> 031440897-0047																		
<b>Sample Description:</b> 1ST LFR BATH/FLR TILE SETTING COMP																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	Gray	0%	100%	None Detected														



# EMSL Analytical, Inc.

307 West 38th Street New York, NY 10018  
Phone/Fax: (212) 290-0051 / (212) 290-0058  
<http://www.EMSL.com> / manhattanlab@emsl.com

EMSL Order ID: 031440897  
Customer ID: ATCE54  
Customer PO: 14-061-0001A  
Project ID:

## Summary Test Report for Asbestos Analysis in Accordance with N.J.A.C. 8:60 and 12:120 via EPA 600/R-93/116

<b>Client Sample ID:</b> 100814-SH-14B	<b>Lab Sample ID:</b> 031440897-0048																		
<b>Sample Description:</b> 1ST LFR BATH/FLR TILE SETTING COMP																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/24/2014	Gray	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-15A	<b>Lab Sample ID:</b> 031440897-0049																		
<b>Sample Description:</b> 1ST LFR BATH/FLR TILE GROUT																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	Gray	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-15B	<b>Lab Sample ID:</b> 031440897-0050																		
<b>Sample Description:</b> 1ST LFR BATH/FLR TILE GROUT																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/24/2014	Gray	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-16A	<b>Lab Sample ID:</b> 031440897-0051																		
<b>Sample Description:</b> 2ND FLR M BATH/FLR TILE SETTING COMP																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	Gray	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-16B	<b>Lab Sample ID:</b> 031440897-0052																		
<b>Sample Description:</b> 2ND FLR M BATH/FLR TILE SETTING COMP																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/24/2014	Gray	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-17A	<b>Lab Sample ID:</b> 031440897-0053																		
<b>Sample Description:</b> 2ND FLR M BATH/FLR TILE GROUT																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	Gray	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-17B	<b>Lab Sample ID:</b> 031440897-0054																		
<b>Sample Description:</b> 2ND FLR M BATH/FLR TILE GROUT																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/24/2014	Gray	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-18A	<b>Lab Sample ID:</b> 031440897-0055																		
<b>Sample Description:</b> 2ND FLR M BATH/WALL TILE SETTING COMP																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	Gray	0%	100%	None Detected														



# EMSL Analytical, Inc.

307 West 38th Street New York, NY 10018  
Phone/Fax: (212) 290-0051 / (212) 290-0058  
<http://www.EMSL.com> / manhattanlab@emsl.com

EMSL Order ID: 031440897  
Customer ID: ATCE54  
Customer PO: 14-061-0001A  
Project ID:

## Summary Test Report for Asbestos Analysis in Accordance with N.J.A.C. 8:60 and 12:120 via EPA 600/R-93/116

<b>Client Sample ID:</b> 100814-SH-18B	<b>Lab Sample ID:</b> 031440897-0056																		
<b>Sample Description:</b> 2ND FLR M BATH/WALL TILE SETTING COMP																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>Tan</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	Tan	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	Tan	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-18C	<b>Lab Sample ID:</b> 031440897-0057																		
<b>Sample Description:</b> BATH # 2/WALL TILE SETTING COMP																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/24/2014	Gray	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-19A	<b>Lab Sample ID:</b> 031440897-0058																		
<b>Sample Description:</b> 2ND FLR M BATH/WALL TILE GROUT																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>White</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	White	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	White	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-19B	<b>Lab Sample ID:</b> 031440897-0059																		
<b>Sample Description:</b> 2ND FLR M BATH/WALL TILE GROUT																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/23/2014</td><td>White</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/23/2014	White	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/23/2014	White	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-19C	<b>Lab Sample ID:</b> 031440897-0060																		
<b>Sample Description:</b> BATH # 2/WALL TILE GROUT																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Gray/White</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	Gray/White	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/24/2014	Gray/White	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-20A	<b>Lab Sample ID:</b> 031440897-0061																		
<b>Sample Description:</b> 2ND FL BATH 2/FLR TILE SETTING COMP																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Gray/White</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	Gray/White	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/24/2014	Gray/White	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-20B	<b>Lab Sample ID:</b> 031440897-0062																		
<b>Sample Description:</b> 2ND FL BATH 3/FLR TILE SETTING COMP																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Brown/Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	Brown/Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/24/2014	Brown/Gray	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-21A	<b>Lab Sample ID:</b> 031440897-0063																		
<b>Sample Description:</b> 2ND FL BATH 2/FLR TILE GROUT																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Tan</td><td>5%</td><td>95%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	Tan	5%	95%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/24/2014	Tan	5%	95%	None Detected														



# EMSL Analytical, Inc.

307 West 38th Street New York, NY 10018  
 Phone/Fax: (212) 290-0051 / (212) 290-0058  
<http://www.EMSL.com> / manhattanlab@emsl.com

EMSL Order ID:	031440897
Customer ID:	ATCE54
Customer PO:	14-061-0001A
Project ID:	

## Summary Test Report for Asbestos Analysis in Accordance with N.J.A.C. 8:60 and 12:120 via EPA 600/R-93/116

<b>Client Sample ID:</b>	100814-SH-21B	<b>Lab Sample ID:</b>	031440897-0064		
<b>Sample Description:</b> 2ND FL BATH 3/FLR TILE GROUT					
TEST	Analyzed Date	Color	Non-Asbestos Fibrous Non-Fibrous	Asbestos	Comment
PLM	10/24/2014	Gray	0% 100%	None Detected	
<b>Client Sample ID:</b> 100814-SH-22A				<b>Lab Sample ID:</b>	031440897-0065
<b>Sample Description:</b> KITCHEN/4" BROWN COVE BASE					
TEST	Analyzed Date	Color	Non-Asbestos Fibrous Non-Fibrous	Asbestos	Comment
PLM	10/24/2014	Brown	0% 100%	None Detected	
<b>Client Sample ID:</b> 100814-SH-22B				<b>Lab Sample ID:</b>	031440897-0066
<b>Sample Description:</b> KITCHEN/4" BROWN COVE BASE					
TEST	Analyzed Date	Color	Non-Asbestos Fibrous Non-Fibrous	Asbestos	Comment
PLM	10/24/2014	Brown	0% 100%	None Detected	
<b>Client Sample ID:</b> 100814-SH-23A				<b>Lab Sample ID:</b>	031440897-0067
<b>Sample Description:</b> KITCHEN/4" COVE BAE MASTIC BRN					
TEST	Analyzed Date	Color	Non-Asbestos Fibrous Non-Fibrous	Asbestos	Comment
PLM	10/24/2014	Brown	8% 92%	None Detected	
<b>Client Sample ID:</b> 100814-SH-23B				<b>Lab Sample ID:</b>	031440897-0068
<b>Sample Description:</b> KITCHEN/4" COVE BAE MASTIC BRN					
TEST	Analyzed Date	Color	Non-Asbestos Fibrous Non-Fibrous	Asbestos	Comment
PLM	10/24/2014	Brown/Tan	0% 100%	None Detected	
<b>Client Sample ID:</b> 100814-SH-24A				<b>Lab Sample ID:</b>	031440897-0069
<b>Sample Description:</b> BASEMENT/PEG BOARD WD- BROWN					
TEST	Analyzed Date	Color	Non-Asbestos Fibrous Non-Fibrous	Asbestos	Comment
PLM	10/24/2014	Brown	85% 15%	None Detected	
<b>Client Sample ID:</b> 100814-SH-24B				<b>Lab Sample ID:</b>	031440897-0070
<b>Sample Description:</b> BASEMENT/PEG BOARD WD- BROWN					
TEST	Analyzed Date	Color	Non-Asbestos Fibrous Non-Fibrous	Asbestos	Comment
PLM	10/24/2014	Brown	97% 3%	None Detected	
<b>Client Sample ID:</b> 100814-SH-25A				<b>Lab Sample ID:</b>	031440897-0071
<b>Sample Description:</b> BASEMENT/9"X9" GRAY FLR TILE					
TEST	Analyzed Date	Color	Non-Asbestos Fibrous Non-Fibrous	Asbestos	Comment
PLM	10/24/2014	Tan	0% 95%	5% Chrysotile	



# EMSL Analytical, Inc.

307 West 38th Street New York, NY 10018  
Phone/Fax: (212) 290-0051 / (212) 290-0058  
<http://www.EMSL.com> / manhattanlab@emsl.com

EMSL Order ID: 031440897  
Customer ID: ATCE54  
Customer PO: 14-061-0001A  
Project ID:

## Summary Test Report for Asbestos Analysis in Accordance with N.J.A.C. 8:60 and 12:120 via EPA 600/R-93/116

<b>Client Sample ID:</b> 100814-SH-25B	<b>Lab Sample ID:</b> 031440897-0072																					
<b>Sample Description:</b> BASEMENT/9"X9" GRAY FLR TILE																						
<table><thead><tr><th>TEST</th><th>Analyzed Date</th><th>Color</th><th colspan="2">Non-Asbestos</th><th>Asbestos</th><th>Comment</th></tr><tr><th></th><th></th><th></th><th>Fibrous</th><th>Non-Fibrous</th><th></th><th></th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Brown</td><td>0%</td><td>94%</td><td>6% Chrysotile</td><td></td></tr></tbody></table>		TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment				Fibrous	Non-Fibrous			PLM	10/24/2014	Brown	0%	94%	6% Chrysotile	
TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment																
			Fibrous	Non-Fibrous																		
PLM	10/24/2014	Brown	0%	94%	6% Chrysotile																	
<b>Client Sample ID:</b> 100814-SH-26A	<b>Lab Sample ID:</b> 031440897-0073																					
<b>Sample Description:</b> BASEMENT/9"X9" FLR TILE MASTIC BLK																						
<table><thead><tr><th>TEST</th><th>Analyzed Date</th><th>Color</th><th colspan="2">Non-Asbestos</th><th>Asbestos</th><th>Comment</th></tr><tr><th></th><th></th><th></th><th>Fibrous</th><th>Non-Fibrous</th><th></th><th></th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Black</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment				Fibrous	Non-Fibrous			PLM	10/24/2014	Black	0%	100%	None Detected	
TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment																
			Fibrous	Non-Fibrous																		
PLM	10/24/2014	Black	0%	100%	None Detected																	
<b>Client Sample ID:</b> 100814-SH-26B	<b>Lab Sample ID:</b> 031440897-0074																					
<b>Sample Description:</b> BASEMENT/9"X9" FLR TILE MASTIC BLK																						
<table><thead><tr><th>TEST</th><th>Analyzed Date</th><th>Color</th><th colspan="2">Non-Asbestos</th><th>Asbestos</th><th>Comment</th></tr><tr><th></th><th></th><th></th><th>Fibrous</th><th>Non-Fibrous</th><th></th><th></th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Brown</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment				Fibrous	Non-Fibrous			PLM	10/24/2014	Brown	0%	100%	None Detected	
TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment																
			Fibrous	Non-Fibrous																		
PLM	10/24/2014	Brown	0%	100%	None Detected																	
<b>Client Sample ID:</b> 100814-SH-27A	<b>Lab Sample ID:</b> 031440897-0075																					
<b>Sample Description:</b> BASEMENT BOILER RM/FLUE CEMENT																						
<table><thead><tr><th>TEST</th><th>Analyzed Date</th><th>Color</th><th colspan="2">Non-Asbestos</th><th>Asbestos</th><th>Comment</th></tr><tr><th></th><th></th><th></th><th>Fibrous</th><th>Non-Fibrous</th><th></th><th></th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment				Fibrous	Non-Fibrous			PLM	10/24/2014	Gray	0%	100%	None Detected	
TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment																
			Fibrous	Non-Fibrous																		
PLM	10/24/2014	Gray	0%	100%	None Detected																	
<b>Client Sample ID:</b> 100814-SH-27B	<b>Lab Sample ID:</b> 031440897-0076																					
<b>Sample Description:</b> BASEMENT BOILER RM/FLUE CEMENT																						
<table><thead><tr><th>TEST</th><th>Analyzed Date</th><th>Color</th><th colspan="2">Non-Asbestos</th><th>Asbestos</th><th>Comment</th></tr><tr><th></th><th></th><th></th><th>Fibrous</th><th>Non-Fibrous</th><th></th><th></th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Brown</td><td>5%</td><td>95%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment				Fibrous	Non-Fibrous			PLM	10/24/2014	Brown	5%	95%	None Detected	
TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment																
			Fibrous	Non-Fibrous																		
PLM	10/24/2014	Brown	5%	95%	None Detected																	
<b>Client Sample ID:</b> 100814-SH-28A	<b>Lab Sample ID:</b> 031440897-0077																					
<b>Sample Description:</b> BASEMENT/2X4 CEILING TILE STREAKED																						
<table><thead><tr><th>TEST</th><th>Analyzed Date</th><th>Color</th><th colspan="2">Non-Asbestos</th><th>Asbestos</th><th>Comment</th></tr><tr><th></th><th></th><th></th><th>Fibrous</th><th>Non-Fibrous</th><th></th><th></th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Gray</td><td>80%</td><td>20%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment				Fibrous	Non-Fibrous			PLM	10/24/2014	Gray	80%	20%	None Detected	
TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment																
			Fibrous	Non-Fibrous																		
PLM	10/24/2014	Gray	80%	20%	None Detected																	
<b>Client Sample ID:</b> 100814-SH-28B	<b>Lab Sample ID:</b> 031440897-0078																					
<b>Sample Description:</b> BASEMENT/2X4 CEILING TILE STREAKED																						
<table><thead><tr><th>TEST</th><th>Analyzed Date</th><th>Color</th><th colspan="2">Non-Asbestos</th><th>Asbestos</th><th>Comment</th></tr><tr><th></th><th></th><th></th><th>Fibrous</th><th>Non-Fibrous</th><th></th><th></th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Brown/White</td><td>70%</td><td>30%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment				Fibrous	Non-Fibrous			PLM	10/24/2014	Brown/White	70%	30%	None Detected	
TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment																
			Fibrous	Non-Fibrous																		
PLM	10/24/2014	Brown/White	70%	30%	None Detected																	
<b>Client Sample ID:</b> 100814-SH-29A	<b>Lab Sample ID:</b> 031440897-0079																					
<b>Sample Description:</b> BASEMENT/2X4 CEILING TILE SMALL HOLE																						
<table><thead><tr><th>TEST</th><th>Analyzed Date</th><th>Color</th><th colspan="2">Non-Asbestos</th><th>Asbestos</th><th>Comment</th></tr><tr><th></th><th></th><th></th><th>Fibrous</th><th>Non-Fibrous</th><th></th><th></th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Gray</td><td>75%</td><td>16%</td><td>9% Amosite</td><td></td></tr></tbody></table>		TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment				Fibrous	Non-Fibrous			PLM	10/24/2014	Gray	75%	16%	9% Amosite	
TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment																
			Fibrous	Non-Fibrous																		
PLM	10/24/2014	Gray	75%	16%	9% Amosite																	



# EMSL Analytical, Inc.

307 West 38th Street New York, NY 10018  
Phone/Fax: (212) 290-0051 / (212) 290-0058  
<http://www.EMSL.com> / manhattanlab@emsl.com

EMSL Order ID: 031440897  
Customer ID: ATCE54  
Customer PO: 14-061-0001A  
Project ID:

## Summary Test Report for Asbestos Analysis in Accordance with N.J.A.C. 8:60 and 12:120 via EPA 600/R-93/116

<b>Client Sample ID:</b> 100814-SH-29B	<b>Lab Sample ID:</b> 031440897-0080																									
<b>Sample Description:</b> BASEMENT/2X4 CEILING TILE SMALL HOLE																										
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Gray/White</td><td>40%</td><td>55%</td><td>5% Amosite</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	Gray/White	40%	55%	5% Amosite								
TEST	Analyzed		Non-Asbestos		Asbestos	Comment																				
	Date	Color	Fibrous	Non-Fibrous																						
PLM	10/24/2014	Gray/White	40%	55%	5% Amosite																					
<b>Client Sample ID:</b> 100814-SH-30A	<b>Lab Sample ID:</b> 031440897-0081																									
<b>Sample Description:</b> FAMILY RM/AIRCELL PIPEINSULATION																										
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Gray</td><td>0%</td><td>45%</td><td>55% Chrysotile</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	Gray	0%	45%	55% Chrysotile								
TEST	Analyzed		Non-Asbestos		Asbestos	Comment																				
	Date	Color	Fibrous	Non-Fibrous																						
PLM	10/24/2014	Gray	0%	45%	55% Chrysotile																					
<b>Client Sample ID:</b> 100814-SH-30B	<b>Lab Sample ID:</b> 031440897-0082																									
<b>Sample Description:</b> LAUNDRY RM/AIRCELL PIPEINSULATION																										
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Gray</td><td>45%</td><td>30%</td><td>25% Chrysotile</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	Gray	45%	30%	25% Chrysotile								
TEST	Analyzed		Non-Asbestos		Asbestos	Comment																				
	Date	Color	Fibrous	Non-Fibrous																						
PLM	10/24/2014	Gray	45%	30%	25% Chrysotile																					
<b>Client Sample ID:</b> 100814-SH-30C	<b>Lab Sample ID:</b> 031440897-0083																									
<b>Sample Description:</b> BASEMENT/AIRCELL PIPEINSULATION																										
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Gray</td><td>35%</td><td>25%</td><td>40% Chrysotile</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	Gray	35%	25%	40% Chrysotile								
TEST	Analyzed		Non-Asbestos		Asbestos	Comment																				
	Date	Color	Fibrous	Non-Fibrous																						
PLM	10/24/2014	Gray	35%	25%	40% Chrysotile																					
<b>Client Sample ID:</b> 100814-SH-31A	<b>Lab Sample ID:</b> 031440897-0084																									
<b>Sample Description:</b> LAUNDRY RM/MUDDED PIPE INSULATION																										
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>White</td><td>3%</td><td>62%</td><td>35% Chrysotile</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	White	3%	62%	35% Chrysotile								
TEST	Analyzed		Non-Asbestos		Asbestos	Comment																				
	Date	Color	Fibrous	Non-Fibrous																						
PLM	10/24/2014	White	3%	62%	35% Chrysotile																					
<b>Client Sample ID:</b> 100814-SH-31B	<b>Lab Sample ID:</b> 031440897-0085																									
<b>Sample Description:</b> BASEMENT/MUDDED PIPE INSULATION																										
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>White</td><td>0%</td><td>47%</td><td>50% Amosite</td><td></td></tr><tr><td></td><td>10/24/2014</td><td></td><td></td><td></td><td>3% Chrysotile</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	White	0%	47%	50% Amosite			10/24/2014				3% Chrysotile	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment																				
	Date	Color	Fibrous	Non-Fibrous																						
PLM	10/24/2014	White	0%	47%	50% Amosite																					
	10/24/2014				3% Chrysotile																					
<b>Client Sample ID:</b> 100814-SH-31C	<b>Lab Sample ID:</b> 031440897-0086																									
<b>Sample Description:</b> BASEMENT/MUDDED PIPE INSULATION																										
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>White</td><td>0%</td><td>60%</td><td>35% Amosite</td><td></td></tr><tr><td></td><td>10/24/2014</td><td></td><td></td><td></td><td>5% Chrysotile</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	White	0%	60%	35% Amosite			10/24/2014				5% Chrysotile	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment																				
	Date	Color	Fibrous	Non-Fibrous																						
PLM	10/24/2014	White	0%	60%	35% Amosite																					
	10/24/2014				5% Chrysotile																					
<b>Client Sample ID:</b> 100814-SH-32A	<b>Lab Sample ID:</b> 031440897-0087																									
<b>Sample Description:</b> BASEMENT BOILER RM/BREECHING INSULATION																										
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>White</td><td>0%</td><td>70%</td><td>30% Chrysotile</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	White	0%	70%	30% Chrysotile								
TEST	Analyzed		Non-Asbestos		Asbestos	Comment																				
	Date	Color	Fibrous	Non-Fibrous																						
PLM	10/24/2014	White	0%	70%	30% Chrysotile																					



# EMSL Analytical, Inc.

307 West 38th Street New York, NY 10018  
Phone/Fax: (212) 290-0051 / (212) 290-0058  
<http://www.EMSL.com> / manhattanlab@emsl.com

EMSL Order ID: 031440897  
Customer ID: ATCE54  
Customer PO: 14-061-0001A  
Project ID:

## Summary Test Report for Asbestos Analysis in Accordance with N.J.A.C. 8:60 and 12:120 via EPA 600/R-93/116

<b>Client Sample ID:</b> 100814-SH-32B	<b>Lab Sample ID:</b> 031440897-0088																		
<b>Sample Description:</b> BASEMENT BOILER RM/BREECHING INSULATION																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>White</td><td>0%</td><td>65%</td><td>35% Chrysotile</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	White	0%	65%	35% Chrysotile	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/24/2014	White	0%	65%	35% Chrysotile														
<b>Client Sample ID:</b> 100814-SH-32C	<b>Lab Sample ID:</b> 031440897-0089																		
<b>Sample Description:</b> BASEMENT BOILER RM/BREECHING INSULATION																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Gray</td><td>0%</td><td>55%</td><td>45% Chrysotile</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	Gray	0%	55%	45% Chrysotile	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/24/2014	Gray	0%	55%	45% Chrysotile														
<b>Client Sample ID:</b> 100814-SH-33A	<b>Lab Sample ID:</b> 031440897-0090																		
<b>Sample Description:</b> EXTERIOR ROOF/TAR PAPER UNDER SLATE																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Black</td><td>85%</td><td>15%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	Black	85%	15%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/24/2014	Black	85%	15%	None Detected														
<b>Client Sample ID:</b> 100814-SH-33B	<b>Lab Sample ID:</b> 031440897-0091																		
<b>Sample Description:</b> EXTERIOR ROOF/TAR PAPER UNDER SLATE																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Black</td><td>80%</td><td>20%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	Black	80%	20%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/24/2014	Black	80%	20%	None Detected														
<b>Client Sample ID:</b> 100814-SH-34A	<b>Lab Sample ID:</b> 031440897-0092																		
<b>Sample Description:</b> KITCHEN- EXT/METAL WINDOW GLAZING																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>White</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	White	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/24/2014	White	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-34B	<b>Lab Sample ID:</b> 031440897-0093																		
<b>Sample Description:</b> KITCHEN- EXT/METAL WINDOW GLAZING																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/24/2014	Gray	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-35A	<b>Lab Sample ID:</b> 031440897-0094																		
<b>Sample Description:</b> LIVING RM/EXT WOOD WINDOW GLAZING																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Brown/White</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	Brown/White	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/24/2014	Brown/White	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-35B	<b>Lab Sample ID:</b> 031440897-0095																		
<b>Sample Description:</b> EAST ENTRANCE/EXT WOOD WINDOW GLAZING																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Gray</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	Gray	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/24/2014	Gray	0%	100%	None Detected														



# EMSL Analytical, Inc.

307 West 38th Street New York, NY 10018  
 Phone/Fax: (212) 290-0051 / (212) 290-0058  
<http://www.EMSL.com> / manhattanlab@emsl.com

EMSL Order ID:	031440897
Customer ID:	ATCE54
Customer PO:	14-061-0001A
Project ID:	

## Summary Test Report for Asbestos Analysis in Accordance with N.J.A.C. 8:60 and 12:120 via EPA 600/R-93/116

<b>Client Sample ID:</b>	100814-SH-36A	<b>Lab Sample ID:</b>	031440897-0096
<b>Sample Description:</b> EXTERIOR/STORM WINDOW CAULK			
<b>Analyzed</b> <b>TEST</b> <b>Date</b> <b>Color</b> <b>Non-Asbestos</b> <b>Fibrous</b> <b>Non-Fibrous</b> <b>Asbestos</b> <b>Comment</b>			
PLM	10/24/2014	White	0%    95%    5% Chrysotile
<b>Client Sample ID:</b> 100814-SH-36B <b>Lab Sample ID:</b> 031440897-0097			
<b>Sample Description:</b> EXTERIOR/STORM WINDOW CAULK			
<b>Analyzed</b> <b>TEST</b> <b>Date</b> <b>Color</b> <b>Non-Asbestos</b> <b>Fibrous</b> <b>Non-Fibrous</b> <b>Asbestos</b> <b>Comment</b>			
PLM	10/24/2014	Gray	0%    96%    4% Chrysotile
<b>Client Sample ID:</b> 100814-SH-37A <b>Lab Sample ID:</b> 031440897-0098			
<b>Sample Description:</b> DINING RM/EXT WOOD WINDW CAULK			
<b>Analyzed</b> <b>TEST</b> <b>Date</b> <b>Color</b> <b>Non-Asbestos</b> <b>Fibrous</b> <b>Non-Fibrous</b> <b>Asbestos</b> <b>Comment</b>			
PLM	10/24/2014	Gray	0%    90%    10% Chrysotile
<b>Client Sample ID:</b> 100814-SH-37B <b>Lab Sample ID:</b> 031440897-0099			
<b>Sample Description:</b> LIVING RM/EXT WOOD WINDW CAULK			
<b>Analyzed</b> <b>TEST</b> <b>Date</b> <b>Color</b> <b>Non-Asbestos</b> <b>Fibrous</b> <b>Non-Fibrous</b> <b>Asbestos</b> <b>Comment</b>			
PLM	10/24/2014	Gray	0%    94%    6% Chrysotile
<b>Client Sample ID:</b> 100814-SH-38A <b>Lab Sample ID:</b> 031440897-0100			
<b>Sample Description:</b> ENTRANCE DOOR/DOOR FRAME CAULK			
<b>Analyzed</b> <b>TEST</b> <b>Date</b> <b>Color</b> <b>Non-Asbestos</b> <b>Fibrous</b> <b>Non-Fibrous</b> <b>Asbestos</b> <b>Comment</b>			
PLM	10/24/2014	Gray	0%    94%    6% Chrysotile
<b>Client Sample ID:</b> 100814-SH-38B <b>Lab Sample ID:</b> 031440897-0101			
<b>Sample Description:</b> ENTRANCE DOOR/DOOR FRAME CAULK			
<b>Analyzed</b> <b>TEST</b> <b>Date</b> <b>Color</b> <b>Non-Asbestos</b> <b>Fibrous</b> <b>Non-Fibrous</b> <b>Asbestos</b> <b>Comment</b>			
PLM	10/24/2014	Gray	0%    96%    4% Chrysotile
<b>Client Sample ID:</b> 100814-SH-39A <b>Lab Sample ID:</b> 031440897-0102			
<b>Sample Description:</b> ATTIC/WOOL LIKE INSULATION			
<b>Analyzed</b> <b>TEST</b> <b>Date</b> <b>Color</b> <b>Non-Asbestos</b> <b>Fibrous</b> <b>Non-Fibrous</b> <b>Asbestos</b> <b>Comment</b>			
PLM	10/24/2014	Tan	90%    10%    None Detected
<b>Client Sample ID:</b> 100814-SH-39B <b>Lab Sample ID:</b> 031440897-0103			
<b>Sample Description:</b> ATTIC/WOOL LIKE INSULATION			
<b>Analyzed</b> <b>TEST</b> <b>Date</b> <b>Color</b> <b>Non-Asbestos</b> <b>Fibrous</b> <b>Non-Fibrous</b> <b>Asbestos</b> <b>Comment</b>			
PLM	10/24/2014	White	87%    13%    None Detected



# EMSL Analytical, Inc.

307 West 38th Street New York, NY 10018  
Phone/Fax: (212) 290-0051 / (212) 290-0058  
<http://www.EMSL.com> / manhattanlab@emsl.com

EMSL Order ID: 031440897  
Customer ID: ATCE54  
Customer PO: 14-061-0001A  
Project ID:

## Summary Test Report for Asbestos Analysis in Accordance with N.J.A.C. 8:60 and 12:120 via EPA 600/R-93/116

<b>Client Sample ID:</b> 100814-SH-40A	<b>Lab Sample ID:</b> 031440897-0104																		
<b>Sample Description:</b> HOUSE INTERIOR/HOUSE WIRE INSULATION BLK																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Black</td><td>75%</td><td>25%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	Black	75%	25%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/24/2014	Black	75%	25%	None Detected														
<b>Client Sample ID:</b> 100814-SH-40B	<b>Lab Sample ID:</b> 031440897-0105																		
<b>Sample Description:</b> HOUSE INTERIOR/HOUSE WIRE INSULATION BLK																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Brown/Gray</td><td>58%</td><td>42%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	Brown/Gray	58%	42%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/24/2014	Brown/Gray	58%	42%	None Detected														
<b>Client Sample ID:</b> 100814-SH-41A	<b>Lab Sample ID:</b> 031440897-0106																		
<b>Sample Description:</b> HOUSE INTERIOR/HOUSE WIRE INSUL WHITE																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Tan</td><td>75%</td><td>25%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	Tan	75%	25%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/24/2014	Tan	75%	25%	None Detected														
<b>Client Sample ID:</b> 100814-SH-41B	<b>Lab Sample ID:</b> 031440897-0107																		
<b>Sample Description:</b> HOUSE INTERIOR/HOUSE WIRE INSUL WHITE																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Brown/Gray</td><td>35%</td><td>65%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	Brown/Gray	35%	65%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/24/2014	Brown/Gray	35%	65%	None Detected														
<b>Client Sample ID:</b> 100814-SH-42A	<b>Lab Sample ID:</b> 031440897-0108																		
<b>Sample Description:</b> FOUNDATION/DAMP PROOF TAR																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Black</td><td>65%</td><td>35%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	Black	65%	35%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/24/2014	Black	65%	35%	None Detected														
<b>Client Sample ID:</b> 100814-SH-42B	<b>Lab Sample ID:</b> 031440897-0109																		
<b>Sample Description:</b> FOUNDATION/DAMP PROOF TAR																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Gray/Black</td><td>0%</td><td>100%</td><td>None Detected</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	Gray/Black	0%	100%	None Detected	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/24/2014	Gray/Black	0%	100%	None Detected														
<b>Client Sample ID:</b> 100814-SH-43A	<b>Lab Sample ID:</b> 031440897-0110																		
<b>Sample Description:</b> EXT GUTTERS/CAULKING/ GUTTERS																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>White</td><td>15%</td><td>80%</td><td>5% Chrysotile</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	White	15%	80%	5% Chrysotile	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/24/2014	White	15%	80%	5% Chrysotile														
<b>Client Sample ID:</b> 100814-SH-43B	<b>Lab Sample ID:</b> 031440897-0111																		
<b>Sample Description:</b> EXT GUTTERS/CAULKING/ GUTTERS																			
<table><thead><tr><th rowspan="2">TEST</th><th colspan="2">Analyzed</th><th colspan="2">Non-Asbestos</th><th rowspan="2">Asbestos</th><th rowspan="2">Comment</th></tr><tr><th>Date</th><th>Color</th><th>Fibrous</th><th>Non-Fibrous</th></tr></thead><tbody><tr><td>PLM</td><td>10/24/2014</td><td>Gray/Black</td><td>0%</td><td>96%</td><td>4% Chrysotile</td><td></td></tr></tbody></table>		TEST	Analyzed		Non-Asbestos		Asbestos	Comment	Date	Color	Fibrous	Non-Fibrous	PLM	10/24/2014	Gray/Black	0%	96%	4% Chrysotile	
TEST	Analyzed		Non-Asbestos		Asbestos	Comment													
	Date	Color	Fibrous	Non-Fibrous															
PLM	10/24/2014	Gray/Black	0%	96%	4% Chrysotile														



# EMSL Analytical, Inc.

307 West 38th Street New York, NY 10018  
Phone/Fax: (212) 290-0051 / (212) 290-0058  
<http://www.EMSL.com> / manhattanlab@emsl.com

EMSL Order ID: 031440897  
Customer ID: ATCE54  
Customer PO: 14-061-0001A  
Project ID:

## Summary Test Report for Asbestos Analysis in Accordance with N.J.A.C. 8:60 and 12:120 via EPA 600/R-93/116

**Client Sample ID:** 100814-SH-44A

**Lab Sample ID:** 031440897-0112

**Sample Description:** BLDG EXTERIOR/REFLECTIVE PA.

TEST	Analyzed		Non-Asbestos		Asbestos	Comment
	Date	Color	Fibrous	Non-Fibrous		
PLM	10/24/2014	White	0%	100%	None Detected	

**Client Sample ID:** 100814-SH-44B

**Lab Sample ID:** 031440897-0113

**Sample Description:** BLDG EXTERIOR/REFLECTIVE PA.

TEST	Analyzed		Non-Asbestos		Asbestos	Comment
	Date	Color	Fibrous	Non-Fibrous		
PLM	10/24/2014	Silver	40%	60%	None Detected	



# EMSL Analytical, Inc.

307 West 38th Street New York, NY 10018  
Phone/Fax: (212) 290-0051 / (212) 290-0058  
<http://www.EMSL.com> / [manhattanlab@emsl.com](mailto:manhattanlab@emsl.com)

EMSL Order ID: 031440897  
Customer ID: ATCE54  
Customer PO: 14-061-0001A  
Project ID:

**Attn:** Ed Fennell  
Cardno ATC  
290 Roberts Street  
Suite 301  
East Hartford, CT 06108

Phone: (860) 282-9924  
Fax: (860) 282-9826  
Collected: 10/ 8/2014  
Received: 10/23/2014  
Analyzed: 10/24/2014

**Proj:** 61.225T3.0020T20070/ CT DCS/ SUPERINTENDENT HOUSE/ SEASIDE HOSP COMPLEX/ 36 SHORE RD  
WATER FORT CT

The samples in this report were submitted for asbestos bulk analysis. The reference number for these samples is the Order ID above. Please use this reference number when calling about these samples.

Sample Receipt Date: 10/23/2014

Sample Receipt Time: 11:52 am

Analysis Completed Date: 10/24/2014

Analysis Completed Time: 10:04 am

## Analyst(s):

Henry Akintunde PLM (44)

Keri-Dean Scarlett PLM (69)

## Reviewed and approved by:

James Hall, Laboratory Manager  
or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. This test report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government. EMSL bears no responsibility for sample collection activities or analytical method limitations. The laboratory is not responsible for the accuracy of results when requested to physically separate and analyze layered samples. PLM alone is not consistently reliable in detecting asbestos in floor coverings and similar NOBs.

Samples analyzed by EMSL Analytical, Inc. New York, NY AIHA-LAP, LLC--IHLAP Accredited #102581, NVLAP Lab Code 101048-9, NYS ELAP 11506, NJ NY022, CT PH-0170, MAAA000170



Shaping the Future

## BULK SAMPLE LOG

Page 1 of 6

290 Roberts Street, Suite 301  
East Hartford, CT 06108  
(860) 282-9924 Fax: (860) 282-9826

031446897

Cardno ATC Inspector:	<u>M. Thompson/S. Szelag</u>	Client Name:	<u>CT PCS</u>
Accreditation No.:	<u>00673/00493</u>	Project No./Task No.:	<u>6/22573.0020 T 20070</u>
Survey Date:	<u>10-8-14</u>	Project Manager:	<u>ED FERRELL</u>
Signature:	<u>J. Szelag</u>	Requested Completion Date:	
Lab Name:	<u>SMS LLC</u>	Requested turnaround time (circle)	<u>3 HR</u>
		3 DY	<u>5 DY</u>
Lab Name:	<u>SUPERINTENDENT HOUSE</u>	Address:	<u>SEASIDE HOSP COMPLEX 30 HORSE RD WATERFORT CT</u>

Location	Material Description	Type S TSI MISC	Estimated Quantity	Friable Y/N	Condition (SD D ND)	Sample of (homogeneous material)	Field Number
1ST FLR FAMILY RM 1/1	RED/BLUE FCR, COURTYARD 1/1	MISC		N		1	100814-5H-117
1ST FLR HAM. RM. 1/1	RED/BLUES FLOOR COATING 1/1	M		N		2	100814-5H-118
KITCHEN 1/1	1/1 SHOWER FLOORING 1/1	M		N		3	100814-5H-119
KITCHEN 1/1	ADHESIVE - TAPE FLOORING 1/1	M		N		4	100814-5H-120
KITCHEN 1/1	3 COAT UPHOLSTERY 1/1	M		N		5	100814-5H-121
M. EXTERIOR 1/1	1-COAT WALL PLAST 1/1	S		N		6	100814-5H-122
1ST FLR JUN Rm 1/1	1-COAT WALL PLAST 1/1	S		N		7	100814-5H-123
2ND FLR HALLWAY 1/1	1-COAT CEMENT PLAST 1/1	S		N		8	100814-5H-124
M. EXTERIOR 1/1	1-COAT WALL PLAST 1/1	S		N		9	100814-5H-125
1ST FLR SIDE RM 1/1	1-COAT WALL PLAST 1/1	S		N		10	100814-5H-126
KITCHEN BDRN-2 1/1	WALL PAINT - SCRATCH COAT 1/1	S		N		11	100814-5H-127
KITCHEN BDRN-2 1/1	WALL PAINT - SCRATCH COAT 1/1	S		N		12	100814-5H-128
Comments:  <u>ALL 8 LBS 189 PCW</u>							

Notes Damage Factors:	Physical (sig drng-dmg-no dmg) Proximity (<1ft-1-6ft->6ft)	Water (extensive-moderate-slight-none) Accessibility (within reach-barely reachable-not reachable)	Deterioration (heavy-moderate-light-none) Vibration (gym-music rm-auditorium-mechanical rm-elevator-other)	Frailility (yes-no): hard-mod-soft surface)
Disturbance Factors:	Ventilation (yes-no, if yes, type)	Air movement (high-moderate-low)	Barriers (perm airtight-enclosed-encapsulated)	Texture (rough-pitted-moderate-smooth)
Relinquished By/Date:	<u>5/29/14</u>	Received By/Date:	<u>5/29/14</u>	Received By/Date:
Relinquished By/Date:				





Shaping the Future

## BULK SAMPLE LOG

290 Roberts Street, Suite 301  
East Hartford, CT 06108  
(860) 282-9924 Fax: (860) 282-9826

Cardno ATC Inspector:	W. Thompson/S. Szczelak	Client Name:	CT DC5					
Accreditation No.:	00673 /00493	Project No./Task No.:	61.22573.0020 T					
Survey Date:	10.8.14	Project Manager:	ED FENNEL					
Signature:	JS/MSL	Requested Completion Date:						
Lab Name:	3 DY 5 DY	Address:	SEASIDE HOSP COMPLEX - SHORE RD WATER FRONT CT					
Building:	Location	Material Description	Type	Estimated Quantity	Friable Y/N	Condition (SD D ND)	Sample of homogeneous material	Field Number
	1ST FLR BATH	FLR TILE STONE COMP	TSI MISC	"	N	"	"	100814-54-191
	"	"	"	"	N	"	"	EMSL 14-148
	1ST FLR BATH	FLR TILE CROUT	"	"	N	"	"	100814-54-192
	"	"	"	"	N	"	"	100814-54-193
	2ND FLR BATH	FLR TILE STONE COMP	"	"	N	"	"	100814-54-194
	"	"	"	"	N	"	"	100814-54-195
	2ND FLR BATH	FLR TILE GROUT	"	"	N	"	"	100814-54-196
	"	"	"	"	N	"	"	100814-54-197
	4TH FLR BATH	WALL TILE STONE COMP	"	"	N	"	"	100814-54-198
	"	"	"	"	N	"	"	100814-54-199
	4TH FLR BATH	WALL TILE GROUT	"	"	N	"	"	100814-54-200
	"	"	"	"	N	"	"	100814-54-201
	4TH FLR BATH	FLR TILE STONE COMP	"	"	N	"	"	100814-54-202
	"	"	"	"	N	"	"	100814-54-203
	4TH FLR BATH	FLR TILE CROUT	"	"	N	"	"	100814-54-204
	"	"	"	"	N	"	"	100814-54-205
	4TH FLR BATH	4" RAILING STONE BASE	"	"	N	"	"	100814-54-206
	"	"	"	"	N	"	"	100814-54-207
	KITCHEN	4" COOK BASE MASTIC BRN	"	"	N	"	"	100814-54-208
					N	"	"	100814-54-209
Comments:	M. = MASSIVE ANALYSIS BY PLM							

Notes	Physical (sig dry-dmg-no smg)	Water (extensive-moderate-slight-none)	Deterioration (heavy-moderate-light-none)
Damage Factors:	Proximity (<1ft - 1-6ft - >6ft)	Accessibility (within reach-barely reachable-not reachable)	Vibration (gym-music rm-auditorium-mechanical rm-elevator-other)
Disturbance Factors:	Air movement (high-moderate-low)	Air movement (high-moderate-low)	Texture (rough-pitted-moderate-smooth)
Ventilation (yes-no, if yes, type)	Elevator shaft - duct	Relinquished By/Date:	Received By/Date:
Relinquished By/Date:	5/26/14 10-22-14	Relinquished By/Date:	Received By/Date:
Comments:	WJ W24/14 3:34 AM		





Shaping the Future

## BULK SAMPLE LOG

Page 5 of 6

290 Roberts Street, Suite 301  
East Hartford, CT 06108  
(860) 282-9924 Fax: (860) 282-9826

081440897

Cardno ATC Inspector:	<u>W. Thompson/S. Szelag</u>	Client Name:	<u>CT PCS</u>				
Accreditation No.:	<u>00673 /00493</u>	Project No./Task No.:	<u>61.22573.0020T</u>				
Survey Date:	<u>10.8.14</u>	Project Manager:	<u>ED FENWELL</u>				
Signature:	<u>S Szelag</u>	Requested Completion Date:					
Lab Name:	<u>EDMOL</u>	Requested turnaround time (circle)	<u>3 HR</u>				
Building:	<u>UPRIGHT INDEPENDENT HOUSE</u>	Address:	<u>SEASIDE HOSP COMPLEX - SHORE RD WATER FRONT CT</u>				
Lab Name:	<u>EDMOL</u>	6 HR	<u>24 HR</u>				
		48 HR					
No. Samples Collected	<u>20</u>						
Location	Material Description	Type TSI MISC	Estimated Quantity	Friable Y/N	Condition (SD D ND)	Sample of (homogeneous material)	Field Number
ITCH ROOM	METAL WINDOW GRATING	m/s	"	Y		2	1008-5H-33A
STORM EXTERIOR	STORM WINDOW FRAME	m/s	"	N		2	1008-5H-33B
INTERIOR	STORM WINDOW CHUTE	m/s	"	N		2	1008-5H-33C
DINING ROOM	EXT WOOD WARD. CUPBOARD	m/s	"	N		2	1008-5H-33D
KITCHEN ROOM	WOOD DOOR FRAME CHUTE	m/s	"	N		2	1008-5H-33E
EXTERIOR DOOR	DOOR FRAME CHUTE	m/s	"	N		2	1008-5H-33F
ATTIC	WOOL WIRE INSULATION	m/s	"	N		2	1008-5H-33G
INTERIOR	HOUSE WIRE INSULATION BACK	m/s	"	N		2	1008-5H-33H
INTERIOR	HOUSE WIRES INSUL, WH/TZ	m/s	"	N		2	1008-5H-33I
FOURTH FLOOR	DAMP PROOF T/F R	m/s	"	N		2	1008-5H-33J
STAIRS	CAD-KNIFE GUTTERS	m	"	N		2	1008-5H-33K
	DOWNSPRINGS	m	"	N		2	1008-5H-33L
Comments:	<u>ASBESTOS</u>						

Notes  
Damage Factors:  
Physical (sig drng-dmg-no drng)  
Proximity (<1ft- 1-6ft->6ft)  
Disturbance Factors:  
Accessibility (within reach-barely  
reachable-not reachable)  
Ventilation (yes-no; if yes,  
type)  
Relinquished By/Date:  
Relinquished By/Date:

Friability (yes-no; hard-mod-soft surface)  
Barriers (perm airtight-enclosed-encapsulated)  
Texture (rough-pitted-moderate-smooth)

Order ID: 031440897  
Received By/Date: SSzelag 10/22/14  
Received By/Date: ED Fenwell 10/23/14  
Deterioration (heavy-moderate-light-none)  
Vibration (gym-music rm-auditorium-mechanical rm-elevator-other)  
Air movement (high-moderate-low)  
Relinquished By/Date: ED Fenwell 10/23/14  
Relinquished By/Date: SSzelag 10/23/14  
S:\BldgSci\Admin\Templates and Forms\Asbestos Bulk Sample Form.doc



**Cardno**<sup>®</sup>  
ATC

Shaping the Future

## BULK SAMPLE LOG

Page 6 of 6

290 Roberts Street, Suite 301  
East Hartford, CT 06108  
(860) 282-9924 Fax: (860)

031440897

**APPENDIX A**  
**LICENSE AND CERTIFICATION**

---

Dear Licensed/Certified Professional,  
 Attached you will find your validated license/certification  
 for the coming year. Should you have any questions about  
 your license/certificate renewal, please do not hesitate to  
 write or call:

**Department of Public Health**      (860) 509-7603  
**P.O. Box 340308**      <http://www.dph.state.ct.us>  
**M.S.#12MQA**

Sincerely,

*Jewel Mullens*

**JEWEL MULLEN, MD, MPH, MPA, COMMISSIONER**  
**DEPARTMENT OF PUBLIC HEALTH**

EMPLOYER'S COPY

STATE OF CONNECTICUT  
 DEPARTMENT OF PUBLIC HEALTH

NAME: STANLEY SZELAG  
 LICENSE NO. 000493  
 CURRENT THROUGH 01/31/15  
 PROFESSION: ASBESTOS CONSULTANT-INSPECTOR

NAME: JEWEL MULLEN  
 LICENSE NO. 03-697205  
 CURRENT THROUGH 01/31/15  
 PROFESSION: ASBESTOS CONSULTANT-INSPECTOR

WALLET CARD  
 STATE OF CONNECTICUT  
 DEPARTMENT OF PUBLIC HEALTH

NAME: STANLEY SZELAG  
 LICENSE NO. 000493  
 CURRENT THROUGH 01/31/15  
 PROFESSION: ASBESTOS CONSULTANT-INSPECTOR

WALLET CARD  
 STATE OF CONNECTICUT  
 DEPARTMENT OF PUBLIC HEALTH

NAME: JEWEL MULLEN  
 LICENSE NO. 03-697205  
 CURRENT THROUGH 01/31/15  
 PROFESSION: ASBESTOS CONSULTANT-INSPECTOR

4. The employer's copy is for persons who must  
 demonstrate current licensure/certification in order  
 to retain employment or privileges. The employer's  
 card is to be presented to the employer and kept by  
 them as a part of your personnel file. Only one copy  
 of this card can be supplied to you.

**INSTRUCTIONS:**

1. Detach and slip each of the cards on this form.
2. Display the large card in a prominent place in your office or place of business.
3. The wallet card is for you to carry on your person. If you do not wish to carry  
 the wallet card, place it in a secure place.

**STATE OF CONNECTICUT**  
**DEPARTMENT OF PUBLIC HEALTH**  
 PURSUANT TO THE PROVISIONS OF THE GENERAL STATUTES OF CONNECTICUT  
 THE INDIVIDUAL NAMED BELOW IS LICENSED  
 BY THIS DEPARTMENT AS A  
 ASBESTOS CONSULTANT-INSPECTOR

STANLEY SZELAG  
 LICENSE NO. 000493  
 CURRENT THROUGH 01/31/15  
 VALIDATION NO. 03-697205

JEWEL MULLEN  
 LICENSE NO. 03-697205  
 CURRENT THROUGH 01/31/15  
 VALIDATION NO. 03-697205

COMMISSIONER

SIGNATURE:

# CERTIFICATE OF ACHIEVEMENT

*This certifies that*

**Stanley Szelag**

*has successfully completed the  
Asbestos Site Inspector Refresher Training  
Asbestos Accreditation Under TSCA Title II  
40 CFR Part 763*

*conducted by*

*Cardno ATC  
73 William Franks Drive  
West Springfield, MA 01089  
(413) 781-0070*

*Gregory J. Monach*

*Principal Instructor*

*April 17, 2014*

*Date of Course*

*April 17, 2015*

*Expiration Date*

*Regional Manager*

*SIAR-4859*

*Certificate Number*

*April 17, 2014*

*Examination Date*

**STATE OF CONNECTICUT**  
 DEPARTMENT OF PUBLIC HEALTH  
 PURSUANT TO THE PROVISIONS OF THE GENERAL STATUTES OF CONNECTICUT  
 THE INDIVIDUAL NAMED BELOW IS CERTIFIED  
 BY THIS DEPARTMENT AS A  
**ASBESTOS CONSULTANT-INSPECTOR**

CERTIFICATE NO.  
**000673**  
 CURRENT THROUGH  
**08/31/16**  
 VALIDATION NO.  
**03-927604**

WILLIE L. THOMPSON  
 SIGNATURE

WILLIE L. THOMPSON  
 SIGNATURE

**INSTRUCTIONS:**

1. Detach and sign each of the cards on this form
2. Display the large card in a prominent place in your office or place of business.
3. The wallet card is for you to carry on your person. If you do not wish to carry the wallet card, place it in a secure place.
4. The employer's copy is for persons who must demonstrate current licensure/certification in order to retain employment or privileges. The employer's card is to be presented to the employer and kept by them as a part of your personnel file. Only one copy of this card can be supplied to you.

WALLET CARD	
STATE OF CONNECTICUT	
DEPARTMENT OF PUBLIC HEALTH	
NAME	
WILLIE L. THOMPSON	
CERTIFICATE NO.	CURRENT THROUGH
<b>000673</b>	<b>08/31/16</b>
VALIDATION NO.	PROFESSION
<b>03-927604</b>	<b>ASBESTOS CONSULTANT-INSPECTOR</b>
SIGNATURE	
<i>Willie Thompson</i>	
COMMISSIONER	

# CERTIFICATE OF ACHIEVEMENT

*This certifies that*

**Willie L. Thompson, III**

*has successfully completed the  
Asbestos Site Inspector Refresher Training  
Asbestos Accreditation Under TSCA Title II  
40 CFR Part 763*

*conducted by*

*Cardno ATC  
73 William Franks Drive  
West Springfield, MA 01089  
(413) 781-0070*

*Edward Kolodziej*

*Principal Instructor: Edward Kolodziej*

*January 23, 2014*

*Date of Course*

*January 23, 2015*

*Expiration Date*

*Gregory D. Marsh*

*Regional Manager: Gregory Marsh*

*SIAR-A760*

*Certificate Number*

*January 23, 2014*

*Examination Date*

**APPENDIX B**  
**DRAWINGS**

---