

Pyrrhotite Impacted Foundations

- Reviewing available data & collaborating with other agencies
- DEEP website to be updated (Crumbling Foundations-links, etc.)
- OLR Report: [Crumbling Concrete Foundations in Connecticut](#) :
(Sept. 19, 2018, 2018-R-0239)
 - Includes background, prohibition, records, disclosure, & links to additional resources
 - Dept. of Consumer Protection: [Deteriorating Concrete Foundations](#)
 - Dept. of Consumer Protection: [Concrete Brochure](#)
 - Dept. of Housing: [Crumbling Foundations](#)
 - Capitol Region Council of Governments: [Foundation Testing](#) & [Crumbling Foundations](#)
- CT Gen. Stat. Sec. 29-265f & 265g prohibitions
- Current common management practices:
 1. On site, BMPs for separation to wells & other sensitive receptors
 2. Off site, non-structure reuse, use as flowable & general fill, landfill

