

2018 IWQR Alternative Approaches to Restoring and Protecting Water Quality

Waterbody Segment ID	Waterbody Name	Impaired Designated Use	Description
CT-C1_019-SB	LIS CB Inner - Housatonic River (mouth), Milford	Habitat for Marine Fish, Other Aquatic Life and Wildlife	Raymark Industries, Inc. <ul style="list-style-type: none"> • Contaminated sediment in Ferry Creek • Action - EPA established Record of Decision to remediate sediment
CT-C1_019-SB	LIS CB Inner - Housatonic River (mouth), Milford	Habitat for Marine Fish, Other Aquatic Life and Wildlife	Stratford Army Engine Plant <ul style="list-style-type: none"> • Contaminated sediment in adjacent tidal flats and tidal ditch • Action – evaluation for the extent of remedial dredging
CT-C2_024	LIS CB Shore - Housatonic River mouth, Stratford	Habitat for Marine Fish, Other Aquatic Life and Wildlife	Sporting Goods Properties, Inc. <ul style="list-style-type: none"> • Contaminated sediment along Lordship Point • Action - evaluation of ecological risk
CT7103-00-2-L3_01	Success Lake (Bridgeport)	Habitat for Fish, Other Aquatic Life and Wildlife	Sporting Goods Properties, Inc. <ul style="list-style-type: none"> • Contaminated sediment within lake • Action - Planned for remedial dredging
CT7103-00-2-L4_01	Stillman Pond (Bridgeport)	Fish Consumption	GE Bridgeport <ul style="list-style-type: none"> • Contaminated sediment within pond • Action - Planned for remedial dredging